
	1 .					IG CHANGE		E				. 1111		
₹ .	<u>.e</u>				DART	EROSPACE L	TD					MIT		
Date: 08.09.11		Job No.:				ADR Yes/No:	N	ADR D	Date:	\mathcal{O}		¢ iv #:	08-	527
Product No.: D120-638, D12						Created By:	1	Approv	/ed By:	IM		#.		521
Product Name: Bearpaw, Wear	plate					Checked By:	P4	Gener	al Manage	r Approval	:			
	ТТ			/ 5	95	1 12								······································
stribution	Reqd	Resp	in	itial / Dat	e	Distribution			Reqd	Resp		Initial	/ Date	
Production Manager	Y	L.L				DQA/QACo			N					
Production Engineering Coord	N					QC Coordina	tor		N	0)44				
Production Document Control	Y	JLD				Marketing	1 5		Y	SW				
Customer Technical Support	 	DS				Customer Or	der Process	sing	N					
<u></u>		1				J <u>L</u>			<u> </u>					
Reason for Change:						***								
RECEIVE EASH ST	<u>C</u>													
Documents Affected:														
Release EASA STC EASA.IM.R.:	S.01451 d	ated 08.0	08.13 for D	120-638										
Release EASA STC EASA.IM.R.	S.01452 d	ated 08.0	08.13 for D	120-639						•				
	DADTO	MHST	COMPLY	,		PREVIOUS	DADTE C	ATICE	ACTOD'	v I				
:	ran i Ş i	IVIOS I ,C	COMPL		х	PREVIOUS	PARISS	AHISE	ACTOR	'				
# Quality Assurance Actions				Reqd	Resp	T		Notes				Cc	omplete	2000
1 Notify Previous Customers	***************************************			N	<u> </u>									De la la
				 										
2 Notify Eurocopter France				N										1.1. 44. 44
3				<u> </u>										Au H
# Engineering Actions				I p	Door			Notes	·	,				
	as Under I	Daviou		Reqd	Resp			Notes					omplete	
4 Required Documents/Drawin- 5 Update Product Compatabilit		Heview		Y	KJ	ļ					/2	810911	14	
				N										
6 Create Eurocopter Form (FEE Notify TC / FAA of Change	=)			N N										· · · · ·
Notify TC / FAA of Change				N		l								
Document Control Actions				Regd	Resp			Notes				Co	mplete	
Document Control Actions 8 Move Electronic Files	· · · · · · · · · · · · · · · · · · ·			Regd N	Resp			Notes				Co	omplete	1
		ronic File	s		Resp KJ			Notes					mplete	PH
8 Move Electronic Files	and Electr	ronic Files	s	N				Notes			0	8,09.1	omplete	Pet
Move Electronic Files Update Blue/Pink/DSI Folder	and Electr			N Y				Notes			0		omplete	Pet
8 Move Electronic Files9 Update Blue/Pink/DSI Folder10 Update Controlled PDF Files	and Electr			N Y N		Add FTR-			0R-120	J-638		8,09.1	omplete	PH A
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (D 13 Update Product Development	and Electr st (MDL) R) t Summary	Revi		N Y N	KJ	Add FTR-	D120-6		OR-120	J-63Z	0	8.09.1 8.09.	i 48	Pet 1
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (D	and Electr st (MDL) R) t Summary	Revi		N N V W	KJ KJ	Add FTR-			OR-120	9-63Z		8.09.1 8.09.1	198	PH S
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (Di 13 Update Product Development	and Electr at (MDL) R) t Summary Approval L	Revi		N N V W	КЈ КЈ	Add FTR-			OR-140	J-637		8.09.1 8.09.	198	Pd A
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update OSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database	and Electronst (MDL) R) t Summary Approval Lee	Revi		N Y N N N Y Y Y Y Y Y Y	KJ KJ KJ	Add FTR-			OR-120	1-638		8,09.1 8,09.1 8,09.1	198	PH A
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record	and Electronst (MDL) R) t Summary Approval Lee	Revi		N Y N N Y Y Y Y N N	KJ KJ KJ	Add FTR-			OR-120	1-638		8,09.1 8,09.1 8,09.1 8,09.1	198	PH S
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update OSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record 18 Create / Update PPP's	and Electrons (MDL) R) t Summary Approval Lese ee ord Form	Rous."	D	N Y N N N N	KJ KJ KJ	Add FTR-			OR-120	J-63Z		8,09.1 8,09.1 8,09.1 8,09.1	198	PH S
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Database 19 Update Document Control Database	and Electrons (MDL) R) t Summary Approval Lese ee ord Form	Rous."	D	N Y N N N N N	KJ KJ KJ KJ	Add FTR-			OR-120	J-63Z		8,09,1 8,09,1 8,09,1 8,09,1	190	PH D
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder	and Electrons (MDL) R) t Summary Approval Lese ord Form	List aminated	D I Dwgs	N Y N N Y N N N N Y	KJ KJ KJ	Add FTR-			DR-120	9-63Z		8,09.1 8,09.1 8,09.1 8,09.1	190	PH D
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update OSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS	and Electrons (MDL) R) t Summary Approval Lese ord Form	List aminated	D I Dwgs	N Y N N N N N	KJ KJ KJ KJ	Add FTR-		38 to				8,09,1 8,09,1 8,09,1 8,09,1	190	PH D
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update OSI 021 and/or STC I 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22	and Electrons (MDL) R) t Summary Approval Lese ord Form	List aminated	D I Dwgs	N Y N N Y N N N N Y	KJ KJ KJ KJ	Add FTR-		38 to		0-638 0 8/09		8,09,1 8,09,1 8,09,1 8,09,1	190	PH D
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update OSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS	and Electrons (MDL) R) t Summary Approval Lese ord Form	List aminated	D I Dwgs	N Y N N Y N N N N Y	KJ KJ KJ KJ	Add FTR-		38 to				8,09,1 8,09,1 8,09,1 8,09,1	190	PH D
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update PSTC Jand/er STC Jupdate Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23	and Electrons (MDL) R) t Summary Approval Lese ord Form	List aminated	D I Dwgs	N Y N N Y N N N N Y	KJ KJ KJ KJ	Add FTR-		33 to				8,09,1 8,09,1 8,09,1 8,09,1	190	PH D
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update PSI 021 and/or STC II 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action:	and Electrons (MDL) R) t Summary Approval Le e e ord Form atabase / L	List aminated	D Dwgs	N Y N N Y Y N N N Y N N N N N N N N N N	KJ KJ KJ KJ KJ		DQ0-6	38 to				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update PSTC Jand/er STC Jupdate Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al	and Electronic (MDL) R) t Summary Approval Le e e ord Form atabase / L. SI/DEO Ma	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N Y N N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	190	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update PSI 021 and/or STC II 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action:	and Electronic (MDL) R) t Summary Approval Le e e ord Form atabase / L. SI/DEO Ma	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N Y N N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le e e ord Form atabase / L. SI/DEO Ma	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N Y N N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (D) 13 Update Product Development 14 Update OSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (D) 13 Update Product Development 14 Update OSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Databas 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10
8 Move Electronic Files 9 Update Blue/Pink/DSI Folder 10 Update Controlled PDF Files 11 Update Master Document Lis 12 Update Document Record (DI 13 Update Product Development 14 Update QSI 021 and/or STC 15 Update Parts / STC Database 16 Update / Verify ARC Database 17 Create / Update Change Record 18 Create / Update PPP's 19 Update Document Control Da 20 Update Grey Project Binder 21 Update D-Part/M-Drawing/DS 22 23 Description / Action: Add EASA.IM.R.S.01451 stc to al Add EASA.IM.R.S.01452 stc to al	and Electronic (MDL) R) t Summary Approval Le electronic electroni	aminated aster Bind	D d Dwgs ders	N Y N N Y Y Y N N N N Y N N N N N N N N	KJ KJ KJ KJ KJ	4 in stock, 4 in p	Digo-6	3 8 + 0 W/K				8,09,1 8,09,1 8,09,1 8,09,1 08,09,	198	P# 10 10 10 10 10 10 10 10 10 10 10 10 10



ENGINEERING CHANGE NOTICE DART AEROSPACE LTD Job No.: Date: 08.09.11 ADR Yes/No: ADR Date: 527 D120-638, D120-639 Product No.: Created By: Approved By: Product Name: Checked By: Bearpaw, Wearplate General Manager Approval: Initial / Date Resp Distribution Reqd stribution Regd Resp Initial / Date Production Manager DQA / QA Coord Ν Production Engineering Coord Ν QC Coordinator Ν Production Document Control Υ JLD SW Marketing Y Customer Technical Support DS Customer Order Processing Ν Reason for Change: RECEIVE EASH SIC **Documents Affected:** Release EASA STC EASA.IM.R.S.01451 dated 08.08.13 for D120-638 Release EASA STC EASA.IM.R.S.01452 dated 08.08.13 for D120-639 PARTS MUST COMPLY х PREVIOUS PARTS SATISFACTORY Quality Assurance Actions Resp Notes Complete Notify Previous Customers Ν Notify Eurocopter France Ν # Engineering Actions Resp Notes Reqd Complete Required Documents/Drawings Under Review KJ Update Product Compatability Matrix Ν Create Eurocopter Form (FEE) Ν Notify TC / FAA of Change Ν **Document Control Actions** Resp Notes Reqd Complete Move Electronic Files 8 Ν 9 Update Blue/Pink/DSI Folder and Electronic Files KJ 10 Update Controlled PDF Files N Update Master Document List (MDL) N Update Document Record (DR) 12 /修 Add FTR-DW0-638 to DR-120-638 13 Update Product Development Summary KJ Update QSI 021 and/er STC Approval List Υ KJ 15 Update Parts / STC Database Υ KJ 16 Update / Verify ARC Database ΚJ Create / Update Change Record Form 17 Ν 18 Create / Update PPP's Ν Update Document Control Database / Laminated Dwgs 19 N 20 Update Grey Project Binder ΚĴ 08.09.1 Update D-Part/M-Drawing/DSI/DEO Master Binders N Description / Action: Add EASA.IM.R.S.01451 stc to all kits in stock and in production: D120-638-011 (4 in stock, 4 in production, B41311)

Add EASA.IM.R.S.01452 stc to all kits in stock and in production: D120-639-011 (4 in stock, 4 in production, B41312)

OK. 9.1 tang beng

DART AEROSPACE

1270 Aberdeen Street Hawkesbury, Ontario K6A 1K7

Transfer Slip

Transfer To:

Hong Kong -Avion Avion Logistics Ltd. Tsuen Wan, N.T, Hong Kong, SAR

Transfer From:

Main Finished Goods Location Dart Aerospace Ltd Hawksbury, Ontario K6A 1K7

MAIN

Reference	Description	Required By
hong kong warehouse	•	' '
		Aug 19, 2008

HONGK

Item Number	Description					Quantity Transferred
-D206 - 642-412	Skidtube RH			•	· · · · · · · · · · · · · · · · · · ·	4.00
	1	B/N: 34060	Chg: CHG004	Qty:	1.00	4.00
		B/N: 34562	Chg: CHG004	Qty:	1.00	1
		B/N: 34564	Chg: CHG004		1.00	
	İ	B/N: 39120	Chg: CHG004	•	1.00	
D206-642-411	Skidtube LH		•	•		4.00
		B/N: 34556	Chg: CHG004	Qtv:	1.00	4.00
		B/N: 34560	Chg: CHG004	Qty:	1.00	
		B/N: 38777	Chg: CHG004		1.00	
		B/N: 38778	Chg: CHG004		1.00	
D206-558-041	Single Cargo Mirror Assembly		•			2.00
	,	B/N: 40748	Chg: CHG007	Qtv:	2.00	2.00
D206549013	Console Assembly		•			2.00
		B/N: 35537	Chg: CHG002	Qty:	1.00	2.00
		B/N: 36075	Chg: CHG002	Qty:	1.00	}
D206-508-011	Antenna Mount		J. 22	,		2.00
		B/N: 30339	Chg: CHG001	Qty:	2.00	2.00
D206-507-011	Shroud Module			~.,·		2.00
		B/N: 38069	Chg: CHG003	Qty:	1.00	2.00
		B/N: 39203	Chg: CHG003	Qty:	1.00	
D205-563 - 041	Cargo Mirror Assembly		ang. amada	,	1.00	2.00
		B/N: 36467	Chg: CHG003	Qty:	2.00	2.00
D204-635-011	Skidtube		5.ig. 5115555	uty.	2.00	2.00
		B/N: 29957	Chg: CHG004	Qty:	1.00	2.00
		B/N: 29959	Chg: CHG004	Qty:	1.00	
D130-700 - 011	Bearpaw		0.1g. 0.10001	- .,.	1.00	2.00
		B/N: 38142	Chg: CHG001	Qtv:	2.00	2.00
D120-639-011	Tungsten Carbide Wearplate		0.1g. 0.10001	٠.,.	2.00	2.00
	and a second sec	B/N: 39554	Chg: CHG002	Qty:	2.00	2.00
0120-638-011	Bearpaw		5/19. 0/10002	Gety.	2.00	0.00
		B/N: 30798	Chg:	Qty:	1.00	2.00
		B/N: 38141	Chg: CHG002	Qty:	1.00	1.
			Ong. 0110002	ωιy.	1.00	
	<u> </u>		····			

"omments:

Continued on next page...

1	The state of the s	
	다. 그 사람들은 사람들이 보고 있다. 그 사람들이 다른 사람들이 되었다. 그 사람들이 다른 사람들이 되었다. 그	
4 1		
	물 · 불功의 실명하다하는 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	
6.4		
	to control the time.	
	The state of the s	
i.		
四 年 第一		
	보다 보고 있는 것이 되었다. 그는 사람들은 사람들은 사람들이 되었다. 그 사람들은 사람들이 되었다. 	in the control of t
		9.

)ART AEROSPACE

Jerdeen Street
 Hawkesbury, Ontario K6A 1K7

Transfer Slip

Date Page Aug 19, 2008 1 Transfer Number TRF0000060

Fransfer To:

Hong Kong -Avion Avion Logistics Ltd.

Tsuen Wan, N.T, Hong Kong, SAR

Transfer From:

Main Finished Goods Location Dart Aerospace Ltd Hawksbury, Ontario K6A 1K7 MAIN

	Description	Required By	
Reference	Description	Aug 19, 2008	
hana kana warehouse		<u> </u>	

HONGK

Item Number	Description					Quantity Transferred
Rem wanton	,					1.00
D407-667-205	Crosstube Aft	B/N: 41197	Chg: CHG006	Qty:	1.00	
	Crosstube Fwd	2 41101	- 13			1.00
D407-667-105	Closstude i wd	B/N: 38989	Chg: CHG002	Qty:	1.00	10.00
634-011	Skidtube		0110005	Ohu	1.00	10.00
1		B/N: 38585	Chg: CHG005	Qty:	1.00	\
		B/N: 38636	Chg: CHG005	Qty:	1.00	
		B/N: 38637	Chg: CHG005	Qty:		
		B/N: 39514	Chg: CHG005	Qty:	1.00	
		B/N: 39517	Chg: CHG005	Qty:	1.00	
	i ·	B/N: 39753	Chg: CHG005	Qty:	1.00	
1	1	B/N: 39987	Chg: CHG005	Qty:	1.00]
	,	B/N: 40142	Chg: CHG005	Qty:	1.00	
		B/N: 40143	Chg: CHG005	Qty:	1.00	ļ
1		B/N: 40146	Chg: CHG005	Qty:	1.00	1
		D/14. 40140	Orig. Cr.Coor	,		6.00
D350-578-011	Bearpaw	B/N: 37246	Chg: CHG005	Qty:	1.00	
,	1		Chg: CHG005	Qty:	5.00	
İ		B/N: 37793	City. Cridoos	Gity.	0,00	5.00
D350-588-011	Aft Door Fwd Hinge Mo	dification	Ob OHO003	Qty:	5.00	0.00
2000 000 011		B/N: 39760	Chg: CHG002	Qty.	5.00	5.00
D206-718-011	Fuel Scupper			٥.	2.00	3.00
D200-710-011		B/N: 24076	Chg:	Qty:	2.00	
	ļ	B/N: 36917	Chg: CHG001	Qty:	3.00	
	Cabin Floor Protector					4.00
D412-760-011	Capilli looi i lotectei	B/N: 38608	Chg: CHG001	Qty:	1.00	ļ
		B/N: 40629	Chg: CHG001	Qty:	3.00	
			ū			3.00
D350-748-201	Crosstube Installation,	B/N: 35734	Chq:	Qty:	1.00	ļ
l .		B/N: 35735	Chg: CHG001	Qty:	1.00	
		B/N: 35736	Chg: CHG001	Qty:	1.00	
		D/N. 33730	Crig. Of 10001	٠.,٠		
1						
į						
					-	

iments:

Continued on next page...

DART AEROSPACE

1270 Aberdeen Street Hawkesbury, Ontario K6A 1K7

Transfer Slip

Date Aug 19, 2008 Page **Transfer Number** TRF0000060

Transfer To:

Transfer From:

Hong Kong -Avion HONGK Avion Logistics Ltd. Tsuen Wan, N.T, Hong Kong, SAR

Main Finished Goods Location Dart Aerospace Ltd Hawksbury, Ontario K6A 1K7

MAIN

Doforono		
Reference	Description	Required By
hong kong warehouse	l	1
		Aug 19, 2008

Item Number	Description					Quantity Transferred
D206-642-412	Skidtube RH					4.00
		B/N: 34060	Chg: CHG004	Qty:	1.00	4.00
		B/N: 34562	Chg: CHG004		1.00	
		B/N: 34564	Chg: CHG004	-	1.00	
		B/N: 39120	Chg: CHG004		1.00	
D206-642-411	Skidtube LH		•			4.00
		B/N: 34556	Chg: CHG004	Qty:	1.00	4.00
]	B/N: 34560	Chg: CHG004	Qty:	1.00	
	1	B/N: 38777	Chg: CHG004	Qty:	1.00	
		B/N: 38778	Chg: CHG004	•	1.00	1
D206-558-041	Single Cargo Mirror Assembly		•			2.00
	1	B/N: 40748	Chg: CHG007	Qty:	2.00	2.00
D206549013	Console Assembly		•			2.00
		B/N: 35537	Chg: CHG002	Qty:	1.00	2.00
		B/N: 36075	Chg: CHG002	Qty:	1.00	
D206-508-011	Antenna Mount			~-y.	1.00	2.00
		B/N: 30339	Chg: CHG001	Qty:	2.00	2.00
D206-507-011	Shroud Module		g	 ,	2.00	2.00
		B/N: 38069	Chg: CHG003	Qty:	1.00	2.00
		B/N: 39203	Chg: CHG003	Qty:	1.00	
D205-563-041	Cargo Mirror Assembly		J. 2	,		2.00
		B/N: 36467	Chg: CHG003	Qty:	2.00	2.00
D204-635-011	Skidtube		5.1g. 5116555	aty.	2.00	0.00
		B/N: 29957	Chg: CHG004	Qty:	1.00	2.00
		B/N: 29959	Chg: CHG004	Qty:	1.00	
D130-700-011	Bearpaw		3.1g. 01.10007	⊶c.y.	1.00	0.00
		B/N: 38142	Chg: CHG001	Qty:	2.00	2.00
D120-639-011	Tungsten Carbide Wearplate	,	J.,g. 0.,0001	y.	2.00	200
	- Samuel Tradițiale	B/N: 39554	Chg: CHG002	Qty:	2.00	2.00
0120-638-011	Bearpaw	,	3.1g. 011000E	æty.	2.00	
		B/N: 30798	Chg:	Qty:	1.00	2.00
		B/N: 38141	Chg: CHG002	Qty:	1.00	
	J		Jing. 0110002	ckty.	1.00	

Comments:

Continued on next page...